

Z

Simbols	Unit of measures	Description
Z		Switching frequency
Z	[1/h]	Permissible starting frequency, loaded
Z ₀	[1/h]	Max. permissible starting frequency, unloaded (I = 50%)